

## **Delta IV Rocket Launch Scrubbed; Second Attempt Wednesday**

---

### **Delta IV Rocket Launch Scrubbed; Second Attempt Wednesday**

The first launch of the Boeing [NYSE:BA] Delta IV rocket was scrubbed this evening because, minutes before liftoff, launch officials detected that a fill valve on the liquid oxygen (LOX) tank did not close, therefore the LOX tank was not properly pressurizing.

Today's launch was scheduled for 5:39 p.m. EST from Space Launch Complex 37B, Cape Canaveral Air Force Station, Fla.

A detailed review of the launch data is underway. Boeing plans a second attempt to launch the Delta IV tomorrow, Wednesday, Nov. 20. The launch window will open at 5:39 p.m. EST and will extend for 70 minutes.

The Boeing Delta IV Medium+ (4,2) rocket is scheduled to launch W5, a commercial telecommunications satellite for Eutelsat S.A.

###

For further information:

Robert Villanueva

(714) 330-1781 Mobile

(714) 372-2089 Office

[robert.s.villanueva@boeing.com](mailto:robert.s.villanueva@boeing.com)

Dan Beck

(562) 810-5797 Mobile

---