

## **Boeing Statement on 787 Center Wing Box**

---

### **Boeing Statement on 787 Center Wing Box**

**EVERETT, Wash., March 20, 2008** -- It is a normal part of the development of a new airplane to discover need for improvements, and that is what we are experiencing on the 787. The robust test process in place on the 787 program has confirmed the majority of our designs but we have found the need for some improvements.

The center wing box issue has been addressed. The fix is being installed on Airplanes 1-6 in the Everett factory. Installations have begun on the four airplanes currently in Final Assembly. All airplanes after Airplane 7 will have the solution incorporated from the beginning.

The fundamental technologies being used on the 787 are proving to be reliable and effective. The material choices and manufacturing techniques for the airplane are sound.

Boeing is working its normal processes for developing a new airplane. The test process is working when issues are discovered and we are reacting appropriately by implementing normal design validation and fixes when we find issues.

###

Contact Info:

Yvonne Leach

787 Communications

206-854-5027

[yvonne.l.leach@boeing.com](mailto:yvonne.l.leach@boeing.com)

---