

## Recommendation for Potential Issue for Some 737 MAX Jets

---

# Recommendation for Potential Issue for Some 737 MAX Jets

**SEATTLE, April 9, 2021** —Boeing has recommended to 16 customers that they address a potential electrical issue in a specific group of 737 MAX airplanes prior to further operations. The recommendation is being made to allow for verification that a sufficient ground path exists for a component of the electrical power system.

We are working closely with the U.S. Federal Aviation Administration on this production issue. We are also informing our customers of specific tail numbers affected and we will provide direction on appropriate corrective actions.

**Contact:**

Boeing Communications

[media@boeing.com](mailto:media@boeing.com)

---